

## Processing Delays PDM1284



SDI Input	1 - 1	Delay V	1 - 1	Delay H	-	AV Delay	-
525	-	0 line	-	12.815 us delayed	   -	1ms	 I
625	i - i	0 line	i - i	13.296 us delayed	i - i	1ms	i
720p50	i - i	0 line	i - i	10.411 us delayed	i - i	1ms	i
1080i50	i - i	0 line	i - i	10.707 us delayed	i - i	1ms	i
720p59	i - i	0 line	i - i	5.918 us delayed	i - i	1ms	i
1080i59	i - i	0 line	i - i	4.799 us delayed	i - i	1ms	i
720p60	i - i	0 line	i - i	5.886 us delayed	i - i	1ms	i
1080i60	i - i	0 line	j - j	4.768 us delayed	i - i	1ms	i
1080sf24	i - i	0 line	i - i	12.269 us delayed	i - i	1ms	i
1080sf23	i - i	0 line	i - i	12.174 us delayed	i - i	1ms	i
1080p29	i - i	0 line	i - i	4.745 us delayed	i - i	0ms	i
1080p25	i - i	0 line	i - i	10.572 us delayed	i - i	0ms	i
1080p24	i - i	0 line	i - i	12.256 us delayed	i - i	0ms	i
1080p23	i - i	0 line	i - i	12.133 us delayed	i - i	0ms	i
1080p50	i - i	0 line	i - i	5.333 us delayed	i - i	1ms	i
1080p59	i - i	0 line	i - i	2.440 us delayed	i - i	1ms	i
1080p60	i - i	0 line	i - i	2.384 us delayed	i - i	1ms	i

## Hint:

• AV measurement inaccuracy varies between -2 ms and 2 ms.