

Processing Delays DVD1823



SDI Input	-	Delay V -	Delay H	-	AV Delay
525	-	0 line -	0.074 us delayed	-	1ms
625	j - j	0 line -	0.037 us delayed	j -	1ms
720p50	j - j	0 line -	0.040 us delayed	j -	1ms
1080150	j - j	0 line -	0.013 us delayed	j -	1ms
720p59	j - j	0 line -	0.027 us delayed	j -	1ms
1080159	j - j	0 line -	0.027 us delayed	j -	1ms
720p60	j - j	0 line -	0.027 us delayed	j -	1ms
1080160	j - j	0 line -	0.027 us delayed	ĺ -	1ms
1080sf24	j - j	0 line -	0.040 us delayed	ĺ -	1ms
1080sf23	j - j	0 line -	0.054 us delayed	ĺ -	1ms
1080p29	j - j	0 line -	0.027 us delayed	ĺ -	0ms
1080p25	j - j	0 line -	0.013 us delayed	ĺ -	0ms
1080p24	j - j	0 line -	0.040 us delayed	ĺ -	0ms
1080p23	j - j	0 line -	0.040 us delayed	ĺ -	0ms
1080p50	j - j	0 line -	0.013 us delayed	ĺ -	1ms
1080p59	j - j	0 line -	0.013 us delayed	ĺ -	1ms
1080p60	-	0 line -	0.027 us delayed	-	1ms

Hint:

• AV measurement inaccuracy varies between -2 ms and 2 ms.